

Lighted Lab Coat™ with Glow-in-the-Park™ technology

OPERATING INSTRUCTIONS

What is Glow-in-the-Park™ technology?

Ruff Wear's Glow-in-the-Park technology provides a light source based on electroluminescence. When the appropriate electric current is applied, the flexible wire glows brightly like a neon light. Amazingly, 1,000 yards of wire consume the energy of just one ordinary light bulb! Electroluminescent wire is bright, colorful, flexible, cool to the touch, energy saving, water-resistant, and weather-durable.

How do I install or change the batteries?

1. Remove the battery pack from the holster on the inside of the coat, behind the size tag.



2. Disconnect the battery pack from the wire by pulling apart the stereo plug connector.



3. Open the battery pack by inserting a coin in the slot and rotating the coin backward.



4. Install two AAA alkaline batteries. Ruff Wear recommends rechargeable batteries to keep the light as bright as possible and to limit the environmental impact of disposables.



5. Reconnect the stereo plug and replace the battery pack in the holster. Make sure the battery pack power button faces the top of the coat and lines up with the power button label. Tuck the stereo plug and any excess wire into the holster.

6. Tightly secure the hook-and-loop fastener on the battery pack holster.

How does the Lighted Lab Coat work?

The power button label on the top of the coat lines up with the battery pack button inside the coat.

- To turn the coat on, PRESS AND HOLD the power button for three full seconds.
- To alternate between *flashing* and *on* modes, press the power button once.
- To turn the coat off, PRESS AND HOLD the power button for three full seconds.

How long will the light stay on?

- In *flashing* mode, your dog will be illuminated for more than 50 hours.
- In *on* mode, your dog will be illuminated for more than 20 hours.

The batteries should be replaced or recharged when the coat shows any reduction in light output.

CARE INSTRUCTIONS

How do I wash the Lighted Lab Coat?

NEVER IMMERSE THE COAT IN WATER WITH THE BATTERY PACK ATTACHED. Disconnect the battery pack and remove from coat. Hand-wash coat in warm water with mild soap. Rinse thoroughly, then hang dry.

Customer Service

luckydog@ruffwear.com
888-783-3932
www.ruffwear.com

Ruff Wear

561 NW York Drive
Bend, OR 97701

